UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO. : 6,910,820 B2

Page 1 of 1

DATED

: June 28, 2005

INVENTOR(S) : Baker, Daniel D.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title page,

Item [56], References Cited, U.S. PATENT DOCUMENTS, add:

-- 4,909,885

3/1990

Swenson --.

Column 4,

Line 63, after "second" insert -- drive motor rotates the driven roller a second surface speed, and where the second --.

Column 9,

Line 65, after "and" insert -- a --.

Column 11,

Line 4, after "speed" insert -- than the platen roller 36, for example preferable at least 101% to 102% of the surface speed --.

Line 61, after "36" insert --, --.

Column 13,

٠٠.

Line 12, after "roller" insert -- 138, which assists in pulling the linerless tape 16 off of the platen roller --.

Line 41, after "tape" insert -- 16 --.

Signed and Sealed this

Third Day of January, 2006

JON W. DUDAS Director of the United States Patent and Trademark Office